

## Deviation from Intended Flightpath Inflight

## Interim Statement

Serious Incident Investigation
Boeing 787-9
A6-BLF
Waypoint RIVER of Hong Kong
7 September 2019

In accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap. 448B), an investigation is in progress to determine the circumstances and causes relating to the serious incident involving an Etihad Airways Boeing 787-9 aircraft, registration A6-BLF, which deviated from the instrument landing system course when it was approaching to Hong Kong International Airport on 7 September 2019.

Based on all collected evidence and information, including those from similar occurrences, the investigation team is analysing the causes of the serious incident and drafting a report on the investigation.

In accordance with paragraph 6.6 of Annex 13 to the Convention on International Civil Aviation, if the report cannot be made publicly available within twelve months, the State/Administration conducting the investigation shall make an interim statement publicly available on each anniversary of the occurrence, detailing the progress of the investigation and any safety issues raised.

7 September 2022

## **Air Accident Investigation Authority Information**

Check the Air Accident Investigation Authority website for information, reports and updates:

https://www.tlb.gov.hk/aaia/eng/investigation\_reports/index.html

The Air Accident Investigation Authority 24/7 Duty Investigator Hotline:

Tel: (852) 9518 5800

Email: ACCID@tlb.gov.hk

Fax: (852) 2910 6049