

**Investigation of Aircraft Accident on Hong Kong Aviation Club
Zlin Z 242 L Aircraft (Registration Mark B-LUK)
on 24 June 2018**

Interim Statement 2/2019

In accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap. 448B), an investigation is in progress to determine the circumstances and causes relating to the accident involving Hong Kong Aviation Club Zlin Z 242 L aircraft (registration mark B-LUK) operated by a private pilot within Ma Shi Chau Special Area, Hong Kong, on 24 June 2018.

Based on all collected evidence, the investigation team is analysing the causes of the accident and drafting the final report on the investigation.

Issued by

Air Accident Investigation Authority

Hong Kong, China

17 June 2019