



Loss of Control

Accident Investigation Interim Statement

Zlin Z 242 L

B-LUK

Hong Kong

24 June 2018

02-2020

In accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap. 448B), an investigation is in progress to determine the circumstances and causes relating to the accident involving a Hong Kong Aviation Club Zlin Z 242 L aircraft (registration mark B-LUK) operated by a private pilot within Ma Shi Chau Special Area, Hong Kong, on 24 June 2018.

Based on all collected evidence, Air Accident Investigation Authority is drafting the investigation report.

In accordance with paragraph 6.6 of Annex 13 to the Convention on International Civil Aviation, if the report cannot be made publicly available within twelve months, the State/Administration conducting the investigation shall make an interim statement publicly available on each anniversary of the occurrence, detailing the progress of the investigation and any safety issues raised.

24 June 2020

Air Accident Investigation Authority Information

Check the Air Accident Investigation Authority website for information, reports and updates:

<https://www.thb.gov.hk/aaia/eng/index.htm>

The Air Accident Investigation Authority 24/7 Duty Investigator Hotline:

Tel: (852) 9518 5800

Email: ACCID@thb.gov.hk

Fax: (852) 2910 6049