



# **Fire/Smoke (Non-impact)**

## **Interim Statement**

**Serious Incident Investigation  
Boeing 747-8F  
N624UP  
Hong Kong International Airport  
20 July 2021**

**10-2022**

In accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap. 448B), an investigation is in progress to determine the circumstances and causes relating to the serious incident involving a United Parcel Service Company (UPS) Boeing 747-8 freighter, registration mark N624UP, departed from the Hong Kong International Airport (VHHH) to the Dubai International Airport (OMDB) on 20 July 2021.

Based on all collected evidence, the investigation team is analysing the causes of the serious incident and drafting the investigation report.

In accordance with paragraph 6.6 of Annex 13 to the Convention on International Civil Aviation, if the report cannot be made publicly available within twelve months, the State/Administration conducting the investigation shall make an interim statement publicly available on each anniversary of the occurrence, detailing the progress of the investigation and any safety issues raised.

20 July 2022

## **Air Accident Investigation Authority Information**

**Check the Air Accident Investigation Authority website for information, reports and updates:**

<https://www.tlb.gov.hk/aaia/eng/index.html>

**The Air Accident Investigation Authority 24/7 Duty Investigator Hotline:**

**Tel: (852) 9518 5800**

Email: [ACCID@tlb.gov.hk](mailto:ACCID@tlb.gov.hk)

Fax: (852) 2910 6049