



# **Dual Hydraulic Systems Failure**

## **Serious Incident Investigation Interim Statement**

**Airbus A330-243  
Hong Kong International Airport  
29 September 2019**

**14-2020**

In accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap. 448B), an investigation is in progress to determine the circumstances and causes relating to the serious incident involving a Hong Kong Airlines Limited Airbus A330-243 aircraft (registration mark B-LHA), flight HX707, of which two hydraulic systems failed after taking off from Runway 25L at the Hong Kong International Airport (VHHH) on 29 September 2019.

Based on all collected evidence, the Air Accident Investigation Authority is analysing the causes of the serious accident.

In accordance with paragraph 6.6 of Annex 13 to the Convention on International Civil Aviation, if the report cannot be made publicly available within twelve months, the State/Administration conducting the investigation shall make an interim statement publicly available on each anniversary of the occurrence, detailing the progress of the investigation and any safety issues raised.

2 November 2020

## **Air Accident Investigation Authority Information**

**Check the Air Accident Investigation Authority website for information, reports and updates:**

<https://www.thb.gov.hk/aaia/eng/index.htm>

**The Air Accident Investigation Authority 24/7 Duty Investigator Hotline:**

**Tel: (852) 9518 5800**

Email: [ACCID@thb.gov.hk](mailto:ACCID@thb.gov.hk)

Fax: (852) 2910 6049