

## **Loss of Control - Inflight**

# Serious Incident Investigation Interim Statement

# Boeing 787-8 Hong Kong International Airport 20 October 2018

### 15-2021

In accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap. 448B), an investigation is in progress to determine the circumstances and causes relating to the serious incident involving an Air India Boeing 787-8 aircraft (registration mark VT-ANE) when it was approaching to Hong Kong International Airport on 20 October 2018.

Based on all collected evidence, the investigation team is analysing the causes of the serious incident and drafting a report on the investigation.

In accordance with paragraph 6.6 of Annex 13 to the Convention on International Civil Aviation, if the report cannot be made publicly available within twelve months, the State/Administration conducting the investigation shall make an interim statement publicly available on each anniversary of the occurrence, detailing the progress of the investigation and any safety issues raised.

20 October 2021

### Air Accident Investigation Authority Information

Check the Air Accident Investigation Authority website for information, reports and updates:

https://www.thb.gov.hk/aaia/eng/index.htm

The Air Accident Investigation Authority 24/7 Duty Investigator Hotline:

#### Tel: (852) 9518 5800

Email: ACCID@thb.gov.hk

Fax: (852) 2910 6049