

民 航 意 外 調 查 機 構

AAIA

Air Accident Investigation Authority



Deviation from Intended Flightpath Inflight

Interim Statement

**Serious Incident Investigation
Boeing 787-8, ET-ASG
Waypoint RIVER of Hong Kong
18 July 2019**

05-2023

In accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap. 448B), an investigation is in progress to determine the circumstances and causes relating to the serious incident involving an Ethiopian Airlines Boeing 787-8 (registration ET-ASG) which deviated from the localizer course while approaching to Hong Kong International Airport on 18 July 2019.

Based on the collected evidence and information, including those from similar occurrences, the investigation team has completed the analysis on the cause of the serious incident. The investigation report is being processed in accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap. 448B).

In accordance with paragraph 6.6 of Annex 13 to the Convention on International Civil Aviation, if the report cannot be made publicly available within twelve months, the State/Administration conducting the investigation shall make an interim statement publicly available on each anniversary of the occurrence, detailing the progress of the investigation and any safety issues raised.

18 July 2023

Air Accident Investigation Authority Information

Check the Air Accident Investigation Authority website for information, reports and updates:

<https://www.tlb.gov.hk/aaia/eng/index.html>

The Air Accident Investigation Authority 24/7 Duty Investigator Hotline:

Tel: (852) 9518 5800

Email: ACCID@tlb.gov.hk

Fax: (852) 2910 6049