

Loss of Control - Inflight (LOC-I)

Interim Statement

Accident Investigation

Ozone Rush 6 Paraglider Pyramid Hill, Hong Kong

26 December 2022

09-2023

In accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap. 448B), an investigation is in progress to determine the circumstances and causes relating to the accident involving an Ozone Rush 6 Paraglider, which descended rapidly towards a bush area in the southeast of Pyramid Hill on December 26, 2022, with the pilot stranded and seriously injured.

Based on all collected evidence and information, the investigation team is analysing the causes of the accident and drafting a report on the investigation.

In accordance with paragraph 6.6 of Annex 13 to the Convention on International Civil Aviation, if the report cannot be made publicly available within twelve months, the State/Administration conducting the investigation shall make an interim statement publicly available on each anniversary of the occurrence, detailing the progress of the investigation and any safety issues raised.

20 December 2023

Air Accident Investigation Authority Information

Check the Air Accident Investigation Authority website for information, reports and updates:

https://www.tlb.gov.hk/aaia/eng/investigation_reports/index.html

The Air Accident Investigation Authority 24/7 Duty Investigator Hotline:

Tel: (852) 9518 5800

Email: ACCID@tlb.gov.hk

Fax: (852) 2910 6049