



# **Aerodrome (ADRM)**

## **Interim Statement**

**Incident Investigation**

**Boeing 737-800BCF**

**VP-BEN**

**Hong Kong International Airport**

**14 October 2021**

**06-2023**

In accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap. 448B), an investigation is in progress to determine the circumstances and causes relating to the incident involving a Siberia Airlines Boeing 737-800BCF, registration mark VP-BEN, departed from Irkutsk Airport, Russia (UIII) to Hong Kong International Airport (VHHH) on 14 October 2021.

Based on all collected evidence and information, the investigation team has completed the analysis on the cause of the incident. The investigation report is being processed in accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap. 448B).

In accordance with paragraph 6.6 of Annex 13 to the Convention on International Civil Aviation, if the report cannot be made publicly available within twelve months, the State/Administration conducting the investigation shall make an interim statement publicly available on each anniversary of the occurrence, detailing the progress of the investigation and any safety issues raised.

13 October 2023

## **Air Accident Investigation Authority Information**

**Check the Air Accident Investigation Authority website for information, reports and updates:**

<https://www.tlb.gov.hk/aaia/eng/index.html>

**The Air Accident Investigation Authority 24/7 Duty Investigator Hotline:**

**Tel: (852) 9518 5800**

Email: [ACCID@tlb.gov.hk](mailto:ACCID@tlb.gov.hk)

Fax: (852) 2910 6049