



# **Loss of Control - Inflight**

## **Interim Statement**

**Serious Incident Investigation  
Boeing 787-8  
VT-ANE  
Hong Kong International Airport  
20 October 2018**

**ITR-2024-07**

In accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap. 448B), an investigation is in progress to determine the circumstances and causes relating to the serious incident involving an Air India Boeing 787-8, registration VT-ANE, when it was approaching to Hong Kong International Airport on 20 October 2018. The aircraft descended rapidly and deviated significantly from the normal glide path triggering a Ground Proximity Warning System alert. The crew recovered the aircraft at about 280 feet radio altitude before performing a go around.

Based on all collected evidence and information, the investigation team has completed the analysis on the cause of the serious incident. The investigation report is being processed in accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap.448B).

In accordance with paragraph 6.6 of Annex 13 to the Convention on International Civil Aviation, if the report cannot be made publicly available within twelve months, the State/Administration conducting the investigation shall make an interim statement publicly available on each anniversary of the occurrence, detailing the progress of the investigation and any safety issues raised.

18 October 2024

## **Air Accident Investigation Authority Information**

**Check the Air Accident Investigation Authority website for information, reports and updates:**

<https://www.tlb.gov.hk/aaia/eng/index.html>

**The Air Accident Investigation Authority 24/7 Duty Investigator Hotline:**

**Tel: (852) 9518 5800**

Email: [ACCID@tlb.gov.hk](mailto:ACCID@tlb.gov.hk)

Fax: **(+852) 2910 6049 (local)**  
**(+852) 3912 4848 (international)**