



Loss of Control - Inflight (LOC-I)

Interim Statement

Accident Investigation

**Ozone Rush 6 Paraglider
Pyramid Hill, Hong Kong**

26 December 2022

ITR-2024-09

In accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap. 448B), an investigation is in progress to determine the circumstances and causes relating to the accident involving an Ozone Rush 6 Paraglider, which descended rapidly towards a bush area in the southeast of Pyramid Hill on December 26, 2022, with the pilot stranded and seriously injured.

Based on all collected evidence and information, the investigation team has completed the analysis on the cause of the incident. The investigation report is being processed in accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap. 448B).

In accordance with paragraph 6.6 of Annex 13 to the Convention on International Civil Aviation, if the report cannot be made publicly available within twelve months, the State/Administration conducting the investigation shall make an interim statement publicly available on each anniversary of the occurrence, detailing the progress of the investigation and any safety issues raised.

23 December 2024

Air Accident Investigation Authority Information

Check the Air Accident Investigation Authority website for information, reports and updates:

<https://www.tlb.gov.hk/aaia/eng/index.html>

The AAIA 24/7 Duty Investigator Hotline:

Tel: (852) 9518 5800

Email: ACCID@tlb.gov.hk

**Fax: (+852) 2910 6049 (local)
(+852) 3912 4848 (international)**