

民 航 意 外 調 查 機 構

AAIA

Air Accident Investigation Authority

Loss of Control - Inflight (LOC-I)

Interim Statement

Accident Investigation

BogdanFly X-wing Paraglider

Sunset Peak, Lantau,

Hong Kong

17 June 2024

ITR-2025-04

In accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap. 448B), an investigation is in progress to determine the circumstances and causes relating to the accident involving a BogdanFly X-wing paraglider which landed on a tree at Sunset Peak on 17 June 2024. The pilot was still strapped in the paraglider and sustained injuries. He was unable to send out his location to his companions. After being located by the search and rescue team, he was transported down the hill in an unconscious state and conveyed to North Lantau Hospital at around 0240 hours on 18 June 2024. He was later certified dead.

Based on all collected evidence and information, the investigation team is analysing the causes of the accident and drafting a report on the investigation.

In accordance with paragraph 6.6 of Annex 13 to the Convention on International Civil Aviation, if the report cannot be made publicly available within twelve months, the State/Administration conducting the investigation shall make an interim statement publicly available on each anniversary of the occurrence, detailing the progress of the investigation and any safety issues raised.

16 June 2025

Air Accident Investigation Authority Information

Check the Air Accident Investigation Authority website for information, reports and updates:

<https://www.tlb.gov.hk/aaia/eng/index.html>

The AAIA 24/7 Duty Investigator Hotline:

Tel: (852) 9518 5800

Email: ACCID@tlb.gov.hk

**Fax: (+852) 2910 6049 (local)
 (+852) 3912 4848 (international)**