

**MTR Platform Screen Door incidents
(2006 - January 2010)**

Date	Station	Damage of glass panel	Cause
18-6-2006	Airport	Cracks found	Human factor
6-10-2006	Yau Ma Tei	Glass panel broken	Human factor
27-11-2006	Tseung Kwan O	Glass panel broken	Impurity contained in glass
12 -1- 2007	Shek Kip Mei	Cracks found	Human factor
22-3-2007	Central	Cracks found	Human factor
18-10-2007	Admiralty	Cracks found	Human factor
21-4-2008	Tiu Keng Leng	Glass panel broken	Impurity contained in glass
11-4-2009	Tsing Yi	Cracks found	Human factor
27-1-2010	Shau Kei Wan	Glass panel broken	Impurity contained in glass