

Turbulence Encounter

Interim Statement

Accident Investigation
Airbus A330-243
Nansha District, Guangzhou City,
Guangdong Province, China
18 June 2019

07-2022

In accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap. 448B), an investigation is in progress to determine the circumstances and causes relating to the accident involving a Hong Kong Airlines Airbus A330-243, registration B-LHA, enroute from Beijing to Hong Kong which encountered turbulence on 18 June 2019.

The investigation team has completed the investigation and disseminated the draft Investigation Report to relevant parties for representation in accordance with Regulation 11, Cap. 448B.

In accordance with paragraph 6.6 of Annex 13 to the Convention on International Civil Aviation, if the report cannot be made publicly available within twelve months, the State/Administration conducting the investigation shall make an interim statement publicly available on each anniversary of the occurrence, detailing the progress of the investigation and any safety issues raised.

10 June 2022

Air Accident Investigation Authority Information

Check the Air Accident Investigation Authority website for information, reports and updates:

https://www.thb.gov.hk/aaia/eng/investigation_reports/index.html

The Air Accident Investigation Authority 24/7 Duty Investigator Hotline:

Tel: (852) 9518 5800

Email: ACCID@thb.gov.hk

Fax: (852) 2910 6049