

Cabin Crew Injury

Accident Investigation Interim Statement

Airbus A330-243
B-LHA
Nansha District, Guangzhou City,
Guangdong Province, China
18 June 2019

09-2021

In accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap. 448B), an investigation is in progress to determine the circumstances and causes relating to the accident involving a Hong Kong Airlines Airbus A330, registration B-LHA, enroute from Beijing to Hong Kong which encountered turbulence on 18 June 2019.

Based on all collected evidence, the investigation team is analysing the causes of the accident and drafting the final report on the investigation.

In accordance with paragraph 6.6 of Annex 13 to the Convention on International Civil Aviation, if the report cannot be made publicly available within twelve months, the State/Administration conducting the investigation shall make an interim statement publicly available on each anniversary of the occurrence, detailing the progress of the investigation and any safety issues raised.

22 July 2021

Air Accident Investigation Authority Information

Check the Air Accident Investigation Authority website for information, reports and updates:

https://www.thb.gov.hk/aaia/eng/index.htm

The Air Accident Investigation Authority 24/7 Duty Investigator Hotline:

Tel: (852) 9518 5800

Email: ACCID@thb.gov.hk

Fax: (852) 2910 6049