



Runway Incursion (RI)

Serious Incident Investigation Interim Statement

**Airbus A330-343 B-LNU and
Boeing 747-867F B-LJK
Hong Kong International Airport
23 December 2017**

18-2021

In accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap. 448B), an investigation is in progress to determine the circumstances and causes relating to the serious incident involving an Airbus A330-343 aircraft (registration mark B-LNU) operated by Hong Kong Airlines Limited (CRK) and a Boeing 747-867F aircraft (registration mark B-LJK) operated by Cathay Pacific Airways Limited (CPA) at the Hong Kong International Airport on 23 December 2017.

Based on all collected evidence, the Air Accident Investigation Authority is analysing the causes of the serious incident.

In accordance with paragraph 6.6 of Annex 13 to the Convention on International Civil Aviation, if the report cannot be made publicly available within twelve months, the State/Administration conducting the investigation shall make an interim statement publicly available on each anniversary of the occurrence, detailing the progress of the investigation and any safety issues raised.

16 December 2021

Air Accident Investigation Authority Information

Check the Air Accident Investigation Authority website for information, reports and updates:

<https://www.thb.gov.hk/aaia/eng/index.htm>

The Air Accident Investigation Authority 24/7 Duty Investigator Hotline:

Tel: (852) 9518 5800

Email: ACCID@thb.gov.hk

Fax: (852) 2910 6049