



# **Multiple Hydraulic System Failure (SCF-NP)**

## **Interim Statement**

**Serious Incident Investigation  
Boeing 747-400F, N406KZ,  
Hong Kong International Airport  
17 June 2024**

**ITR-2026-04**

In accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations (Cap. 448B), an investigation is in progress to determine the circumstances and causes relating to the serious incident involving an Atlas Air Boeing 747-400F freighter, registration mark N406KZ, at Hong Kong International Airport (VHHH) on 17 June 2024 (Hong Kong local time).

Based on all collected evidence and information, the investigation team is analysing the causes of the serious incident and drafting the investigation report.

In accordance with paragraph 6.6 of Annex 13 to the Convention on International Civil Aviation, if the report cannot be made publicly available within twelve months, the State/Administration conducting the investigation shall make an interim statement publicly available on each anniversary of the occurrence, detailing the progress of the investigation and any safety issues raised.

16 June 2026

### **Air Accident Investigation Authority Information**

**Check the Air Accident Investigation Authority website for information, reports and updates:**

<https://www.tlb.gov.hk/aaia/eng/index.html>

**The AAIA 24/7 Duty Investigator Hotline:**

**Tel: (852) 9518 5800**

**Email: [ACCID@tlb.gov.hk](mailto:ACCID@tlb.gov.hk)**

**Fax: (+852) 2910 6049 (local)  
(+852) 3912 4848 (international)**